## **CLAIMS**

- 1. (cancelled)
- 2. (cancelled)
- 3. (cancelled)
- 4. (cancelled)
- 5. (previously amended) A method of using a seismic detector including four seismic sensors having axes which are in a substantially tetrahedral configuration, to detect and measure seismic activity, each of the sensors being in a respective signal channel, the method including the step of checking the gains of the four channels by taking a plurality of samples from the sensors, constructing a set of simultaneous equations from the samples, and solving the equations to determine the gains of the four channels.
- 6. (previously amended) A method of using a seismic detector including four seismic sensors having axes which are in a substantially tetrahedral configuration, to detect and measure seismic activity, each of the sensors being in a respective signal channel, the method including the following steps:
  - a) <u>combining combing</u> outputs from the sensors to check that their polarities are correct;
  - b) testing to ascertain if one of the sensors is not working and, if so, using the outputs from the other three sensors to obtain an indication of motion in three dimensions;
  - c) if all four sensors are working, using their outputs to obtain an indication of motion in three dimensions on a least squares basis;
  - d) checking that the outputs from the sensors are coherent; and
  - e) checking the gains of the four channels.